



Welding inverter **TIG 200i AC/DC**



STANDARD EQUIPMENT:

- welding cable
- TIG torch
- return cable
- mask & brush

No	Order code	Description	Quantity
1	0302006018S001	plastic handle	1
2	0302006018S002	outer shell	1
3	0302006018S003	Primary inverter board	1
4	0302006018S004	PFC inductor	1
5	0302006018S005	Motherboard fixing plate	1
6	0302006018S006	rear panel	1
7	0302006018S007	plastic back panel	1
8	0302006018S008	External force cable gland	1
9	0302006018S009	power harness	1
10	0302006018S010	connecting screw	1
11	0302006018S011	Air valve harness	1
12	0302006018S012	rocker switch	1
13	0302006018S013	Motherboard fixing plate right	1
14	0302006018S014	Fan wiring harness	1
15	0302006018S015	Conductive sheet	1
16	0302006018S016	Secondary inverter board	1
17	0302006018S017	Chassis board	1
18	0302006018S018	Conductive sheet	1
19	0302006018S019	High voltage arc ignition plate	1
20	0302006018S020	output bus 2	1
21	0302006018S021	Output bus four	1
22	0302006018S022	Hall harness	1
23	0302006018S023	Argon gas fitting	1
24	0302006018S024	Aviation socket	1
25	0302006018S025	potentiometer knob	1
26	0302006018S026	quick socket	2
27	0302006018S027	plate support plate	1
28	0302006018S028	panel control panel	1
29	0302006018S029	plastic front plate	1
30	0302006018S030	main control board	1
31	0302006018S031	output bus one	1
32	0302006018S032	main fixing plate	2

