



Welding inverter **TIG 200i**



STANDARD EQUIPMENT:

- welding cable
- TIG torch
- return cable
- mask & brush

No	Order code	Description	quantity
1	0302006017S001	plastic handle	1
2	0302006017S002	outer shell	1
3	0302006017S003	EMC filter board	1
4	0302006017S004	IGBT inverter board	1
5	0302006017S005	Movement bracket	1
6	0302006017S006	high frequency board	1
7	0302006017S007	plastic front plate	2
8	0302006017S008	shutters	2
9	0302006017S009	panel	1
10	0302006017S010	panel fixing plate	1
11	0302006017S011	potentiometer knob	1
12	0302006017S012	Aviation socket wiring harness	1
13	0302006017S013	Argon gas fitting	1
14	0302006017S014	quick socket	2
15	0302006017S015	Hall current sensor	1
16	0302006017S016	machine foot	4
17	0302006017S017	ground bar	1
18	0302006017S018	chassis	1
19	0302006017S019	Arc pilot plate holder	1
20	0302006017S020	rectifier plate	1
21	0302006017S021	PFC inductor	1
22	0302006017S022	PFC board	1
23	0302006017S023	DC fan	1
24	0302006017S024	Fan air deflector	1
25	0302006017S025	Fixed panel on rear panel	2
26	0302006017S026	Clamping plate	1
27	0302006017S027	rocker switch	1
28	0302006017S028	Solid external force cable fixed head	1
29	0302006017S029	Power cord harness	1
30	0302006017S030	Air valve harness	1

