

WME_m LYNX Expert W177 welding inverter


SPARE PARS LIST



STANDARD EQUIPMENT:

- welding cable
- return cable

SPARE PARTS LIST WME_m 177



SPARE PARTS LIST WMEm 177

NO.	Order code	Name	Unit	Qty
1	301602032S001	Backstraps	PCS	1
2	301602032S002	Shell	PCS	1
3	301602032S003	Bottom plate metal	PCS	1
4	301602032S004	Decorative cover plate	PCS	1
5	301602032S005	Indicator light socket	PCS	2
6	301602032S006	Potentiometer knob	PCS	1
7	301602032S007	Digital display meter	PCS	1
8	301602032S008	Quick socket copper parts	PCS	1
9	301602032S009	Output copper bar 2	PCS	1
10	301602032S010	Output copper bar 1	PCS	1
11	301602032S011	Main board (Pure board, no components)	PCS	1
12	301602032S012	Intermediate frequency transformer	PCS	1
13	301602032S013	Fast recovery diode	PCS	4
14	301602032S014	Quick recovery tube radiator	PCS	1
15	301602032S015	Plastic support column2	PCS	1
16	301602032S016	IGBT radiator 2	PCS	1
17	301602032S017	Plastic support column 1	PCS	1
18	301602032S018	Radiator	PCS	1
19	301602032S019	Rectifier bridge	PCS	1
20	301602032S020	IGBT	PCS	4
21	301602032S021	Electrolytic capacitor	PCS	4
22	301602032S022	DC fan	PCS	1
23	301602032S023	Fan mesh cover	PCS	1
24	301602032S024	Rocker switch	PCS	1
25	301602032S025	16A style plug,	PCS	1